

BUILDING SAFETY CERTIFICATE

No.: 763

Dated: 17.05.2023

Certified that the existing building **Bhanmati Devi Global Academy** (name of the building or premises) at **Aksara Beili, Basti- 272302 (U.P.)** (Address) comprised of **1091.50 sq. mtrs.** (Ground floor) and **1091.50 sq. mtrs.** (First floor) owned/occupied by **Bhanmati Devi Global Academy** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **PWD, Basti** (Name of Department/ Govt.) on **15.05.2023** (date of inspection) in the presence of **Mr. Shyam Lal Chaudhary R/o Vill- Bhojar (Chakdaha), Post- Kalwari, Dist.- Basti** (Name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy upto **classes XII** with effect from **17.05.2023** for a period of **20 years** in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on **17.05.2023** at **Basti** by **PWD, Basti**.

Signature with Seal: **अधिशसी अधियन्ता**
प्रान्तीय खण्ड लोअमिजविअ,

Name: **वस्ती**

Designation: _____

Name & Address of Department/ Office: _____

(Assistant Engineer & above officer of concerned Govt. Department only)

Principal

Bhanmati Devi Global Academy
 Aksara, Baili, Basti (U.P.)

Manager

Bhanmati Devi Global Academy
 Aksara, Baili, Basti (U.P.)